

J. IMMANUEL KOILRAJ
B.E, F.I.E, M.I.S.T.E, M.I.S.E,
F.I.V, A.S.C.E, C.Eng.,
Chartered Engineer & Reg. Govt. Approved Valuer
Licensed Surveyor & Loss Assessor.
Valuer- W10/CC IT KOL-XI/CIT/128/CAT-I/2009-10

SC/JIK/C/4885/2026

10.04.2026

STABILITY CERTIFICATE

This is to certify that the School building of **St. Paul's School (English Medium School)**, constructed at Survey No. 418/14/1 at Wimberlygunj, Ferrargunj Tehsil, South Andaman has been inspected by us on 10.04.2026.



The Building is RCC Semi structure and Single Storey Building. Footpaths, Ground etc are safe. The tubular trusses erected for covering of building was inspected by me. The structural arrangement/ members provided in the said Tubular post, Rafters, purling and cleats are found to be reasonable. There are no visual distresses visible in the structural members. The quality of construction seems to be acceptable.



Based on the enquiries made to the clients and the information provided by them, and upon my judgment, it is found that the School Building is safe for occupation.

Latitude & Longitude: 11.738267, 92.71438



J. IMMANUEL KOILRAJ
Chartered Engineer &
Reg. Govt. Approved valuer.

J. IMMANUEL KOILRAJ
B.E, F.I.E, M.I.S.T.E, M.I.S.E,
F.I.V, A.S.C.E, C.Eng.
Licensed Surveyor & Loss Assessor
Approved Valuer & Chartered Engineer
No.3 Saginara Complex,
Prem Nagar, Port Blair.





LAYOUT MAP



J. IMMANUEL KOILRAJ
B.E, F.I.E, M.I.S.T.E, M.I.S.E,
F.I.V, A.S.C.E, C.Eng.,
Chartered Engineer & Reg. Govt. Approved Valuer
Licensed Surveyor & Loss Assessor.
Valuer- W10/CC/IT KOL-XI/CI/128/CAT-1/2009-10

SC/JIK/C/4885/2026

10.04.2026

STABILITY CERTIFICATE

This is to certify that the School building of **St. Paul's School (English Medium School)**, constructed at Survey No. 418/14/1 at Wimberlygunj, Ferrargunj Tehsil, South Andaman has been inspected by us on 10.04.2026.

The Building is RCC Semi structure and Single Storey Building. Footpaths, Ground etc are safe. The tubular trusses erected for covering of building was inspected by me. The structural arrangement/ members provided in the said Tubular post, Rafters, purling and cleats are found to be reasonable. There are no visual distresses visible in the structural members. The quality of construction seems to be acceptable.


Based on the enquiries made to the clients and the information provided by them, and upon my judgment, it is found that the School Building is safe for occupation.


Latitude & Longitude: 11.738267, 92.71438

J. IMMANUEL KOILRAJ
Chartered Engineer &
Reg. Govt. Approved valuer.

F.I.E, F.I.V, M.I.S.T.E
B.E, A.S.C.E, C.Eng
Licensed Surveyor & Loss Assessor
Approved Valuer & Chartered Engineer
No.3, Sagittara Complex,
Prem Nagar, Port Blair.

LAYOUT MAP





Wimberlygunj, Andaman And Nicobar Islands, India


Ppq7+9rv, Wimberlygunj, Andaman And Nicobar Islands
744206, India

Lat 11.73864° Long 92.714432°

Friday, 10/04/2026 09:56 AM GMT +05:30

Google

GPS Map Camera



Wimberlygunj, Andaman And Nicobar Islands, India

Ppq7+9rv, Wimberlygunj, Andaman And Nicobar Islands
744206, India

Lat 11.738398° Long 92.71435°

Friday, 10/04/2026 09:56 AM GMT +05:30

Google

GPS Map Camera

